

# Oil Field Environmental Incident Summary

**Incident:** 20141115164625      **Date/Time of Notice:** 11/15/2014 16:46

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:** ONEOK ROCKIES MIDSTREAM

**Well Name:** East of Long 112-1H

**Field Name:**

**Well File #:**

**Date Incident:** 11/15/2014      **Time Incident:** 13:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 99

**Sec:** 1

**Qtr:** NW NW

**Location Description:** This location is east if the Long 112-1H well site on 54th

**Submitted By:** Kim Rudningen

**Received By:**

**Contact Person:** Kim Rudningen  
2700 Lincoln Ave SE  
Sidney, MT 59270

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Pipeline ROW

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	5	Barrels				

**Description of Other Released Contaminant:**

Natural gas condensates

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There are no immediate risks associated with this release.

**Areal Extent:**

This has affected the topsoil 15 ft in diameter around the blowout location.

**Potential Environmental Impacts:**

this release has impacted top soil immediately around the location of the blowout. The condensate has frozen and is not in danger of leaving the location. there is no impact to waterways or surface water.

**Action Taken or Planned:**

the line was immediately blown down, a crew has been lined up to assist with cleanup and repair of the line. All contaminated soils will be removed to a certified landfill.

**Wastes Disposal Location:** all recovered wastes will be hauled to a certified disposal location.

**Agencies Involved:** Local Law Enforcement  
Williams County Dispatch

**Updates**

---

**Date:** 11/17/2014 **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Pipelines are under NDDoH oversight. Followup is necessary.

---

**Date:** 6/10/2015 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 4:42 6/10/2015.

No sign of impacts at the time of inspection.

No follow up is necessary.